

TOPIC: Replacing Cartridge Oil Filter R2651P

Care should be taken when removing the R2651P cartridge oil filter to ensure the perforated core in the filter cap isn't accidentally discarded.

When replacing R2651P ensure the perforated core/sleeve remains inside the filter cap and **NOT** still inside the old filter.

It is easily removed with the filter because the OE perforated sleeve is only seated in a groove at the bottom of the filter cap.

If the cartridge filter is fitted with out the core the cartridge will collapse.

The sleeve is not supplied as a replaceable consumable with the filter ... **always check the filter core prior to the filter disposal.**



AUSTRALIA

Ryco Group Pty Ltd
29 Taras Avenue, Altona North
Victoria 3025 Australia.
www.rycofilters.com.au

NEW ZEALAND

Ryco Group - A division of GUD NZ Holdings Ltd
19 Bell Avenue, Otahuhu
Auckland, New Zealand
www.ryco.co.nz

SOCIAL NETWORKS

Facebook: facebook.com/rycofilters
Instagram: instagram.com/rycofilters
YouTube: youtube.com/RycoFiltersAus
Twitter: twitter.com/Ryco_Filters