


RYCO

F I L T E R S



Ryco N99 MicroShield® ***Cabin Air Filter***

In-vehicle air purification against biological contaminants



Ryco MicroShield



Anti-Viral



Anti-Bacterial



Medical Grade Media



Odour Barrier



≤ 0.3 Micron

RYCO

F I L T E R S



Ryco N99 MicroShield® Cabin Air Filter

In-vehicle air purification against biological contaminants

Breathe with Confidence

The biggest threat to safe breathing inside your vehicle can be 40 times smaller than the width of a human hair and invisible. The easiest way to protect a vehicle's passengers from airborne contaminants is to fit a Ryco MicroShield Cabin Air Filter with N99 media.



Anti-Viral

Anti-Viral agents within the media eliminate airborne virus* from the air flow.

*H1N1/H3N2



Anti-Bacterial

Anti-bacterial agents within the media eliminate bacteria from the air flow and stops it growing in the filter



Anti-Mould

Stops mould and fungus spores growing in the filter



Pollen

Captures pollens that aggravate allergies, asthma and hay fever




Dust & Dirt

Captures dust and dirt particles to keep the vehicle interior surfaces cleaner




Odour Barrier

Protects vehicle occupants from harmful exhaust gases, noxious odours, soot and smog



Ryco MicroShield

N99 medical grade media layer with 99.7% efficiency @ 0.3 micron. Tested to ISO11155-2:2009




≤0.3 Micron

Captures miniscule particles that can penetrate deeper into the respiratory system



Replacement

Replace the Ryco Cabin Air Filter at least once a year or every 15,000 km



Ryco MicroShield Protection

Ryco Microshield Cabin Air Filters consist of three levels of protection against biological contaminants.

1. Anti-viral layer with natural polyphenol extracts eliminate virus, bacteria and allergens
2. Activated carbon odour and gas absorption/barrier
3. Medical grade melt-blown electrostatically charged 0.3 micron layer

Ryco N99 MicroShield® Cabin Air Filter

In-vehicle air purification against biological contaminants



Upgraded MicroShield Filters In Store October 2020

Part No.	Location	Approx. Fitment Time	Major Applications
RCA100M	Passenger side behind the glove box	15 min	FORD Falcon, Fairlane (BA, BF, FG, FG II), Territory
RCA104M	Passenger side behind the glove box	20 min	SUBARU Liberty, Outback; TOYOTA Avensis, Celica, Prius, Tarago
RCA107M	Passenger side behind the glove box	20 min	HYUNDAI Getz
RCA108M	Passenger side behind the glove box	20 min	HONDA Accord Euro & 9th Gen, Civic 9th Gen Legend, Odyssey
RCA112M	Front passenger foot well, underneath the dash	20 min	VOLKSWAGEN Amarok, Multivan, Touareg, Transporter T5; AUDI Q7
RCA113M	Passenger side behind the glove box	20 min	LEXUS IS and GS; NISSAN X-Trail (T30), Maxima (J31), Murano, Patrol (Y61), Pulsar (N16)
RCA140M	Passenger side behind the glove box	15 min	TOYOTA Corolla - ZZE122R, ZZE123R, Echo, Prius, RAV4, Yaris
RCA149M	Passenger front foot well, underneath the dash	20 min	AUDI A3, Q3, TT; VOLKSWAGEN Beetle, Caddy van, EOS, Golf, Jetta, Tiguan, Passat; SKODA Yeti
RCA162M	Passenger side, vehicle engine bay, below windscreen	15 min	HOLDEN Commodore/Berlina/Calais (VE), Statesman/Caprice (WM); HSV Clubsport, Grange (GEN F) Senator (E Series)
RCA164M	Passenger side behind the glove box	15 min	LEXUS RX270, LS400; TOYOTA Aurion, Camry, Kluger, Prius, RAV4; SUBARU Liberty, Outback
RCA173M	Passenger side behind the glove box	20 min	KIA Cerato (TD), Grand Carnival (VQ), Sorrento (XM)
RCA174M	Passenger side behind the glove box	30 min	NISSAN Navara D40 (Spanish built), Pathfinder (R51)
RCA182M	Passenger side behind the glove box	15 min	ALFA ROMEO 159, Brera, Spider; HOLDEN Colorado RG; MITSUBISHI ASX, Lancer CJ, Outlander ZG & ZH; MU-X; PEUGEOT 4008; ISUZU D-Max
RCA183M	Passenger side behind the glove box	20 min	SUBARU Impreza, Forester, XV
RCA185M	Passenger side behind the glove box	15 min	HYUNDAI Accent, Genesis, i40, Veloster, IX35; KIA Rio (JB & UB), Sportage
RCA201M	Passenger side behind or underneath the glove box	15 min	HYUNDAI i45, Santa Fe; KIA Optima
RCA206M	Passenger side behind or underneath the glove box	20 min	MITSUBISHI Challenger (PB, PC), Grandis, Lancer (CH), Outlander (ZF), Triton ML, MN
RCA207M	Passenger footwell behind centre console lower trim	45 min	FORD Focus (LS, LT, LV)
RCA211M	Passenger side behind the glove box	15 min	HYUNDAI Elantra (MD), i30; KIA Cerato, Rondo, Pro_ceed
RCA223M	Passenger side behind the glove box	20 min	HONDA Legend KB, Honda Civic 9th Gen
RCA224M	Passenger side behind the glove box	15 min	HOLDEN Barina TM, Cruze JG & JH, Trax; OPEL Astra PJ & Insignia GA
RCA227M	Passenger side behind the glove box	15 min	FORD Everest UA, Ranger PX; MAZDA BT50 UPOY
RCA230M	Passenger side behind the glove box	20 min	NISSAN Navara (D40) Thai built
RCA232M	Passenger footwell behind centre console lower trim	30 min	MAZDA 3 BL (All)
RCA240M	Passenger side behind the glove box	15 min	HYUNDAI i30 FD
RCA242M	Passenger side behind the glove box	20 min	JEEP Grand Cherokee WK 3.6I V6 & 5.7I V8
RCA246M	Passenger footwell behind centre console lower trim	15 min	MADZA Mazda 2 (DE)
RCA248M	Passenger side behind the glove box	15 min	SUZUKI Swift FZ, RS415 & RS416
RCA251M	Passenger side behind the glove box	15 min	HONDA Jazz (GE & GD) from 04/06
RCA252M	Passenger side behind the glove box	20 min	MITSUBISHI Pajero, NT, NW, NM & NP
RCA267M	Passenger side behind the glove box	20 min	RENAULT FLUENCE, NISSAN JUKE (F15) , PULSAR (B17, C12)
RCA270M	Passenger side behind the glove box	15 min	AUDI A3 (8V); SKODA Octavia (NE); VOLKSWAGEN Golf (VII);
RCA275M	Passenger side behind the glove box	15 min	MAZDA CX-5, 3 (BM)
RCA287M	Passenger footwell behind centre console lower trim	35 min	FORD Focus LW I & II, Kuga
RCA329M	Passenger footwell behind centre console lower trim	20 min	NISSAN X-Trail T32
RCA333M	Passenger side behind the glove box	15 min	Toyota Hilux GUN125/126R