

Fitting Information about R2833P

The R2833P Fuel Filter is designed to be with its attached cap. This ensures that the rubber seal is aligned to the outlet pipe inside the housing.

Extra care is recommended when fitting this filter to ensure the bottom rubber seal - critical to the filter's performance is not dislodged.

The element has the cap attached to it so it can be lined up in the housing, as you start screwing the filter, the seal will dock perfectly.

Removing the filter cap is not recommended prior to fitment as it can cause misalignment and possible damage to the bottom rubber seal. The rubber seal has been designed with a softer rubber compound to optimise its sealing performance given that it is a 4-micron filter.



AUSTRALIA

Ryco Group Pty Ltd
29 Taras Avenue, Altona North
Victoria 3025 Australia.
www.rycofilters.com.au

NEW ZEALAND

Ryco Group - A division of GUD (NZ) Holdings Limited
Othahuhu, Auckland, New Zealand
www.ryco.co.nz

SOCIAL NETWORKS

Facebook: <http://facebook.com/rycofilters>
YouTube: www.youtube.com/c/RycofiltersAus
Instagram: <https://www.instagram.com/rycofilters>
Twitter: http://twitter.com/Ryco_Filters